

EN 208V CONTROL MODULE / COOLING FAN SERVICE KITS

The information provided in this document is intended for trained, qualified personnel only. The proper function and the safety of the appliance can be affected by an improper repair, and even serious threats to life or physical condition may arise. BSH Home Appliances Corporation is not liable for damages caused by improper repairs performed by unauthorized parties. Local codes and standards apply and must be observed. Contact the Technical Support Team for further assistance.

The 208V Control Module / Cooling Fan Service Kits are offered for the Bosch built-in wall ovens and slide-in ranges identified in the table below, which meet **ALL** of the following conditions...

1. FD date prior to 9405.
2. Installed on a 208V circuit.
3. Wall oven or range is not operational due to burned out cooling fan, E302 / E118 error, and/or high-temp cutout tripped.

To repair, replace the control module and cooling fan with the parts included in the service kit, and reset the HTC near the door latch. **Both parts in the kit must be installed to ensure proper operation.**

Model (FD Prior to 9405)	Service Kit Part No.	Model (FD Prior to 9405)	Service Kit Part No.	Model (FD Prior to 9405)	Service Kit Part No.
HBL5351UC/01	11003178	HBLP451RUC/01	11003184	HDI8054C/01	11003437
HBL5451UC/01	11003179	HBLP451UC/01	11003184	HDI8054U/01	11003437
HBL5551UC/01	11003180	HBLP651LUC/01	11003185	HDIP054C/01	11003437
HBL5651UC/01	11003181	HBLP651RUC/01	11003185	HDIP054U/01	11003437
HBL5751UCC/01	11003179	HBLP651UC/01	11003185	HEI8054C/01	11003186
HBL8451UC/01	11003182	HBLP751UCC/01	11003184	HEI8054U/01	11003186
HBL8461UC/01	11003182	HBN5451UC/01	11003179	HEIP054C/01	11003186
HBL8651UC/01	11003183	HBN5651UC/01	11003181	HEIP054U/01	11003186
HBL8661UC/01	11003183	HBN8451UC/01	11003182	HIIP054C/01	11003186
HBL8751UCC/01	11003182	HBN8651UC/01	11003183	HIIP054U/01	11003186
HBLP451LUC/01	11003184	HSLP751UCC/01	11003184		

For authorized servicers, additional assistance is available by contacting our Technical Support Team at (800) 444-9091.

Visit *QuickFinder* at <http://portal.mch.bshg.com/portal>.