

Information Document Affected Bosch Appliances

BSH HOME APPLIANCES GROUP

Identity of Affected Bosch Appliances

Bosch

BSH Home Appliances Ltd is conducting a voluntary safety campaign regarding two models of built-in gas hobs. The reason is potential damage to installed gas connectors. In certain circumstances, gas can escape in an uncontrolled manner and in extremely rare cases a risk of explosion can arise.

BSH is offering every owner of an affected appliance a free replacement of the gas connector by an authorised service engineer at the owner's home. BSH requests all customers of a product listed above to check whether their appliance is affected by this safety campaign.

Please note: To avoid any potential hazard until the gas connector is replaced, owners of an affected appliance should turn off the gas supply to the appliance and no longer use it.


We apologise for any inconvenience caused. If you have trouble checking whether your appliance is affected or if you have any further questions, please contact us via the website or by calling the free phone number.

Identity of Affected Bosch Appliances

Bosch

- NGU4151DB
- NGU4151DB/01
- NGU4151DB/02
- NGU4151DB/03
- NGU4151DB/04
- NGU4151DB/05

FD from 8901 up to and including 9110



Appliance Identification


Bosch NGU4151DB

The appliance E.Nr number and FD number can be found on the original user manual. This can be found on the front or rear of the manual.

Alternatively the E.Nr number and FD number can be found on the Rating Plate of the appliance. This is located on the underside of the hob.

A model is affected if the E.Nr number is NGU4151DB, and the FD number is in range 8901-9110.

If the consumer does not have the user manual or cannot gain access to the underside of the hob. Please use the enclosed documentation to identify a potentially affected appliance.



Appliance Identification

Following each of these steps, if the appliance is not affected then no further clarification is needed.

Appliance Size



Potentially affected models are 60cm wide with a stainless steel top **only.**

Hobs with other coloured tops are not affected.



Position of Control Knobs

Possible affected models have the controls on the right side of the appliance **only.**

If the appliance has the control knobs in another location then the_appliance is **not affected.**



This appliance is **possibly affected** as controls are on the **right side**.




This appliance is **not affected** as the controls are on the **front**.

Burners



Possible **affected** models have 4 standard single flame burners.



Models with dual flame wok-style burner are not affected.

Bosch Logo





An appliance is **possibly affected** if the **logo** is situated in the **top right hand corner** and the logo is printed in black.

An appliance is **not affected** if the **logo** is either engraved or situated on the **bottom right corner.**

Pan supports

Distinctive pan supports – combination of:

- 1. Thin gloss black coated pan supports
- 2. Specific left and right hand location:
- Distinctive rounded corners at the rear
- Squarer corners at the front
- Pan supports cannot be rotated 180°. (Non-rotational)



Printing



Printing in and around the ignition position is unique to this appliance with solid tapering black lines.

Appliances with the **solid tapering black line are possibly affected.**



Appliances with the following features are not affected.

- 1. Printing in and around the ignition position has a simple single line
- 2. Printing in and around the ignition position is pressed into the metal not printed in black

Please note: To avoid any potential hazard until the gas connector is replaced, owners of an affected appliance should turn off the gas supply to the appliance and no longer use it.

We apologise for any inconvenience caused. If you have trouble checking whether your appliance is affected or if you have any further questions, please contact us via the website or by calling the free phone number.

www.gascookingsafety.com

BSH Home Appliances Limited,

Grand Union House, Old Wolverton Road, Wolverton, Milton Keynes, MK12 5PT BSH Home Appliances Group is a Trademark Licensee of Robert Bosch GmbH for the brand Bosch.

Free phone UK: 0800 0287 260 Free phone Ireland: 1800 855 833